

2. Hardness measurement of small bearing ball quenching

Hardness of about 1mm diameter bearing ball quenching is measured by putting the ball on a square type sensor, using the amplifier which outputs phase and amplitude of signal emitted by a test material.

From the graph in which x-axis is amplitude and y-axis phase, it is seen that different hardness materials are distributed separately.

