

5. Non-destructive inspection of electron beam welded gear

Cogs and base of a gear are electron beam welded. It is possible to see the quality of welding penetration by putting the sensor on welded part.

