## 9. Non destructive inspection of sintered metal crack

Putting the sintered metal rod ( $12\times80$ ) into the middle of the ring-sensor, sintered metal crack is inspected. At A-2 the MDK-value shows clearly positive with the qualified rod, the non-qualified rods instead show minus, so that the qualification distinction can be made very easily.

