

1. Detecting defects on a steel pipe covered with heat insulating material

Non-destructive inspection is conducted by a large square type sensor to detect defects on a steel pipe covered with 100mm thick insulating material. This insulating material is covered with 1mm thick metal plate.

The result is that two defect points are confirmed on the graph. This clarifies that the magnetism generated by the sensor reaches the steel pipe.

